





SS

TRACK LIGHT SYSTEM


## INSTALLATION GUIDE




## STEP 1.



## STEP 2.




## STEP 3.



## NOTES

1. All track seams must be secured with flat connector in order to ensure perfect alignment
2. L shape track must use 2 flat connectors, one for each side, in order to ensure proper alignment

\*\*All track are field cuttable at any point





SS

## TRACK LIGHT SYSTEM

## STEP 3.

Power Connectors must be placed in center of each track seam for power to travel from track to track

①



Starting Wire

②



Hard Connector

③



Hard L Connector

④



Flexible L Connector

